May 13, 1976

Rad. Health/ Land Survey Mission Oaks S/D

G. F. Zimmermann Inc. 1628 South Florida Avenue Post Office Box 2036 Lakeland, Florida 33803

Dear Sir:



Attached you will find the rough gamma radiation survey of the above referenced property. Other than some reading taken on lots at the request of the owner(s) these readings were taken within the public right-of-way only. At your written request we will do a complete survey of this property. As you will note the recommended levels are as follows:

Interim Recommendations For Gamma Exposure Levels At New Structures Sites on Florida Phosphate Lands

External Gamma Radiation Level

Recommendations

Equal or greater than 0.01 mR/hr

Construction should be delayed pending additional study or acceptable control technology should be instituted to preclude indoor radon daughter problems

Less than .01 mR/hr.

Construction may be initiated

As you will note quite a few of those readings obtained were in excess of the recommended levels. Should you wish to discuss this further or discuss the possibility of utilizing control technology in the structures please do not hesitate to contact me.

Sincerely,


Donald R. Guthrie, P.E. Sanitary Engineer


DRG: mnk


FIELD REPORT ON Mission Oaks	19-18-18-18-18-18-18-18-18-18-18-18-18-18-
TOWN VISITED Bartow	DATE May, 1976
OWNER OF PROPERTY	PERSON SEEN_
BY WHOM Harlan Keaton & Lee Forgey	TIME SPENT 2 hours
REASON FOR VISIT GAMMA SURVEY	

REPORT:

LOCATION #	GAMMA READING (Micro R/hr)
15	20
16	18
17	18
18	17
19	26
20	18
21	18
22	26
23	20
24	17
25	17
26	15
27	18
28	. 21
29	23
30	23
31	35
32	33
33	23
34	25
35	20
36	17
37	19
38	35
39	25
40	26
41	19
42	18
SAN 17 43	17
44	16
45	25
46	17
40	1 /









Parkview Lake Estates **S** ③ (E) Avenin (P) **(b)** HERMOSA


FIELD REPORT ON Mission DAKS & PANKVIEW	LAKE Estates
TOWN VISITED Bantow	DATE April 14415
OWNER OF PROPERTY	PERSON SEEN
BY WHOM HANIAN KEALON & LEE Fongey	TIME SPENT Thours
	& Phosphale Land
Cocation Mynr location Mynr 10.2 REPORT: 1. 18.4 12. 12.1 2. 18.4 23. 8.2 3. 22.3 24. 20.5 4. 20.5 25. 21.3 5. 22.3 27. 24.2 6. 27.9 29. 18.6 7. 24.2 29. 18.6 9. 24.2 30. 37.2 8. 31.4 31. 29.8 9. 24.2 32. 32. 32.3 10. 20.5 34. 29.8 11. 20.5 34. 29.8 12. 24.2 35. 18.6 13. 22.3 36. 18.6 14. 24.2 35. 18.6 15. 20.5 37. 24.2 16. 18.6 39. 24.2 16. 18.6 39. 24.2 16. 18.6 39. 24.2 16. 18.6 39. 24.2	
18. 18.4 19. 13.8 20. 17.4 SAN 17	




@ - 22.5 38-14,5 (10) - 26. V 34-30,6 35-20.4 11-22.0 36-18.8 12- 23.5 37-19,2 13- 2115 14-22.7 15-20,5 39-2613 16-21.7 1 40-18.1 17-21.8 41-21.7 18-19.5 12-20.2 43-21.0 19-14,3 20-12.9 44-221/ 21-10.8 45-24.4 -22-12.3 16-20.2 23 - 8,3 21-22.0 1-20.0 75-22.7 2-2015 26-20.2 3-23.4 27-21.2 4-230 28-18.0 5.245 29- 19.7 6.20.7 30-37.2 7-23.9 3-37-8 31-28.5 32-22,9

Mission OAKS Rendre George St. MISSION DAY 27 32







May 13, 1976

Rad. Health/ Land Survey Parkview Lake Ests. S/D

Mr. Ronny Jones

(b) (6)

Dear Mr. Jones:

Attached you will find the rough gamma radiation survey of the above referenced property. Other than some reading taken on lots at the request of the owner(s) these readings were taken within the public right-of-way only. At your written request we will do a complete survey of this property. As you will note the recommended levels are as follows:

Interim Recommendations For Gamma Exposure Levels At New Structures Sites on Florida Phosphate Lands

External Gamma Radiation Level

Equal or greater than 0.01 mR/hr

Less than .01 mR/hr

Recommendations

Construction should be delayed pending additional study or acceptable control technology should be instituted to praclude indoor radon daughter problems


Construction may be ini-

As you will note quite a few of those readings obtained were in excess of the recommended levels. Should you wish to discuss this further or discuss the possibility of utilizing control technology in the structures please do not hesitate to contact me.

Sincerely,

Donald R. Guthrie, P.E. Sanitary Engineer

FIELD REPORT ON PARKVIEW LAKE ESTAT	RS
TOWN VISITED Bartow	DATE May, 1976
OWNER OF PROPERTY	PERSON SEEN
BY WHOM Harlan Keaton & Lee Forgey	TIME SPENT 2 hours
REASON FOR VISIT CAMMA SURVEY	
REPORT:	
LOCATION #	GAMMA READING (Micro R/hr)
1 2 3 4 5 6 7 8	16 18 18 20 18 18 18
9 10 11 12 13 14 47 48 49 50 51 52 53	25 38 38 21 19 18 20.5 24.2 26.0 22.3 20.5 22.3 18.6 18.6





DEPARTMENT OF HEALTH AND REHABILITATIVE SERVICES STATE OF FLORIDA

Reubin O'D Askew, Governor Field Report

POLK COUNTY HEALTH DEPARTMENT

DISTRICT OFFICES

1788 HOLLAND PKWY., SOUTH BARTOW, FLORIDA 33830

P. O. BOX 691 HAINES CITY, FLORIDA 33644

P, O, BOX 334 LAKE WALES, FLORIDA 33883

103 EAST CANAL STREET MULBERRY, FLORIDA 33660 WILLIAM F. HILL, JR., M.D.

P. O. BOX 1460 229 AVENUE D. N.W. WINTER HAVEN, FLORIDA 33880

May 13, 1976

Rad. Health/ Land Survey Parkview Lake Ests. S/D DISTRICT OFFICES

1333 NORTH FLORIDA AVE. LAKELAND, FLORIDA 33801

P, O, BOX 33 WAVERLY, FLORIDA 33877

2 NORTH REEDY BLVD. PROSTRPOOF, FLORIDA 33843

243 E. LAKE AVENUE AUBURNDALE, FLORIDA 33823

Mr. Ronny Jones (b) (6)

Dear Mr. Jones:

Attached you will find the rough gamma radiation survey of the above referenced property. Other than some readings taken on lots at the request of the owner(s) these readings were taken within the public right-of-way only. At your written request we will do a complete survey of this property. As you will note the recommended levels are as follows:

Interim Recommendations For Gamma Exposure Levels
At New Structures Sites on Florida Phosphate Lands

External Gamma Radiation Level

Equal or greater than 0.01 mR/hr

Less than .01 mR/hr

Recommendations

Construction should be delayed pending additional study or acceptable control technology should be instituted to preclude indoor radon daughter problems

Construction may be initiated

As you will note quite a few of those readings obtained were in excess of the recommended levels. Should you wish to discuss this further or discuss the possibility of utilizing control technology in the structures please do not hesitate to contact me.

Sincerely,

Donald R. Guthrie, P.E.

Sanitary Engineer


DRG:mnk


FIELD REPORT ON PARKVIEW LAKE ESTATES				
TOWN VISITED Bartow	DATE May, 1976			
OWNER OF PROPERTY	PERSON SEEN			
BY WHOM Harlan Keaton & Lee Forgey	TIME SPENT 2 hours			
REASON FOR VISIT GAMMA SURVEY				
REPORT:				
LOCATION # GAMMA READING	(Micro R/hr)			
1 16 2 18 3 18 4 20 5 18 6 18 7 18 8 12 9 25 10 38 11 38 12 21				
12 13 14 18 47 20 48 49 26 50 50 22 51 20 52 51 20 22 51 20 22 51 20 21 22 23 24 25 26 27 28 28 28 28 28 28 28 28 28 28	.2 .0 .3 .5 .3			

Field Report

FIELD REPORT ON	Mission 0A	Ks + Pank	View LAKE	Fotates	
TOWN VISITED Ra	antow Phillips		DATE	May 6,19	76
OWNER OF PROPERTY			PERSON/SE	EN S	
BY WHOM HARIAN	Keaton vi	ee Fonsey	TIME SPEN	T 2 hour	3
REASON FOR VISIT	GAMMA S	ariew 07	Reclaime	d Phosip	hate land.
Cocation Gam REPORT: Lumber IN	ma Reading				2-15: 32
1-16			10 - 16 11 - 16	CONTRACTOR OF THE PARTY OF THE	3- H
2-jij () () () () () () () () () (13 × 20	一、「「「「「「」」」「「」」「「」「「」」「「「」」「「」」「「」」「「」」「	4-145
3-18 12-20			24/12	Compression of the second con-	(S25)
35.15			15-17 I		16-111-2
10518			20+15 27-18		17-20.5
יי צווברו און יי			28-21	11 A THE LAND CO. L.	48-24.2.
δ=12-			29-23		49-26.0
9-25			(30°-23 (314435°-)		50= 22.3:
11-38			32-33		51-2015
			332.23	经国际证券 计图象图象	52-22-3
3279			31-25		53-18.6
A PARTY			835-20 36-17	第 555 1855 1855 1855 1855 1855 1855 1855	54-18.6
13715-20-1					, , , , , , , , , , , , , , , , , , , ,
72/8			38-35		
18:17			37-15		
15-20			31-19. 38-35 39-25 40-26 41-19		
20+18					
san 17					







(b) (6)

(mann rd.

BTW)

2 Owners: (b) (6)

Mr. Hanlow

from. B.M. Dimos Kickn